



S0250016
TASK ID #6644
cc: Lynn

5-21-15

Application for Bond Release

Operator/Permittee: <u>ALPINE GEMS LLC / ALPINE GEMS MINERALS</u>	
Mine/Project Name: <u>BUTLER VALLEY</u>	Permit ID#: <u>S/025/0016</u>
	Permitted Acres: <u>5 AC.</u>
Reason for Bond Release: <u>RECLAMATION COMPLETED, VEGETATIVE GROWTH COMPLETE.</u>	
Amount of Existing Surety: <u>\$22,500 - \$18,000 (ALREADY RELEASED) = \$4,500</u>	
Amount of Surety requested for release: <u>\$4,500</u>	
Partial Release of a <u>portion</u> * of the mine site: Acres Regraded: Specify Area:	Partial Release of <u>entire</u> mine site: (Backfilling and grading are completed) Acres: <u>5 ACRES.</u>
Full Release of a <u>portion</u> * of the mine site: Acres to be released: Specify Area:	Full Release of <u>entire</u> mine site: (Vegetation is established and has survived three growing seasons.) Acres to be released: <u>5 ACRES.</u>
*For a bond release on a portion of the mine site, submit an updated map removing the released area from the disturbed or bonded area.	



Application for Bond Release

Reclamation practices must be completed in accordance with R647-2-109, or R647-3-109, or R647-4-111 as applicable.

Have any shafts and tunnels been permanently sealed?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	<i>NOT APPLICABLE</i>
Disposal of debris & other materials incident to mining	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Public safety notifications such as posted signs or fences/barriers above high walls	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	<i>NOT APPLICABLE</i>
Drainages, reestablished & stable	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Structures demolished and deleterious materials disposed of	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	<i>NOT APPLICABLE, NO STRUCTURES</i>
Erosion Controlled	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Slopes, waste piles, fills regraded	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Highwalls stabilized to an angle of 45° or less	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Meets Post mining Land Use (Indicate Land use)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	<i>GRAZING, RECREATION</i>
Roads and/or pads have been reclaimed	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Dams, Impoundments, Ditches, Pits reclaimed	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Topsoil redistributed – amendments added	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Vegetation meets 70% of the pre-mining cover?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
<p><i>Note: For Final Bond Release vegetation must meets 70% of premining cover and has survived three years for or has survived one year growing season to maintain small mine status.</i></p>		
Plugging of boreholes	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	<i>NOT APPLICABLE</i>
<p>If Answer is Yes, please fill out page 3 of this form</p>		
<p>DESCRIPTION of RECLAMATION ACTIVITIES COMPLETED (Describe any variance(s) that have been granted, date activity completed)</p>		



o:\forms\bonding forms\bond-release\mr-site rev2014.doc